

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

J83
WSW
1/8-1/4
0.165 mi.
870 ft.

INTERSECTION; TRANSFORMER VAULT
STILLWELL AVE AND NEPTUNE AVE
BROOKLYN, NY

NY Spills S110308580
N/A

Site 10 of 14 in cluster J

Relative:
Higher

Actual:
2 ft.

SPILLS:

Name: INTERSECTION; TRANSFORMER VAULT
Address: STILLWELL AVE AND NEPTUNE AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1001270 / 2010-08-24
Facility ID: 1001270
Facility Type: ER
DER Facility ID: 389187
Site ID: 434309
DEC Region: 2
Spill Cause: Unknown
Spill Class: D4
SWIS: 2401
Spill Date: 2010-05-03
Investigator: RWAUSTIN
Referred To: Not reported
Reported to Dept: 2010-05-03
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False

UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2010-05-03
Spill Record Last Update: 2010-08-24
Spiller Name: Not reported
Spiller Company: UNK
Spiller Address: Not reported
Spiller Company: 999
Contact Name: ERT
DEC Memo: "8/24/10 - Austin - Leaking transformer was removed - Spill contained and cleaned up by Con Ed - see Docs for EMIS report - spill closed - end"

Remarks: "10 gallons of an unknown petroleum was spilled onto 1000 gallons of water; clean up is pending sample results; no waterways affected"

All Materials:

Site ID: 434309
Operable Unit ID: 1185147
Operable Unit: 01
Material ID: 2179441
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: Not reported
Oxygenate: Not reported